

GM CUSTOMER CARE AND AFTERSALES
DCS3461
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 25, 2014

Subject: Upcoming Safety Recall – Bulletin # 14291
Low Beam Headlamps And Daytime Running Lamps Could Fail To
Illuminate

Models: 2006-2009 Buick LaCrosse
2006-2008 Buick Rainier
2006-2007 Chevrolet Trailblazer
2006-2008 Chevrolet Trailblazer EXT
2006-2007 GMC Envoy
2006-2008 GMC Envoy XL
2006-2008 Saab 9-7X

To: Buick, Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,

General Motors has notified the National Highway Traffic Safety Administration (NHTSA) about an upcoming safety recall that involves certain 2006-2009 model year Buick LaCrosse and Rainier, Chevrolet Trailblazer and Trailblazer EXT, GMC Envoy and Envoy EXT and Saab 9-7X vehicles. The GM recall number is 14291.

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2006 – 2009 model year Buick LaCrosse vehicles; certain 2006 – 2008 Saab 9-7X vehicles; certain 2006 – 2007 Buick Rainier, Chevrolet Trailblazer and GMC Envoy vehicles; and certain 2006 Chevrolet Trailblazer EXT and GMC Envoy XL vehicles. The headlamp driver module (HDM) in certain of these vehicles may not operate properly in the thermal environment of the underhood electrical center. If the HDM is not operating correctly, the low-beam headlamps and daytime running lamps could fail to illuminate. This failure could be intermittent or permanent. This condition does not affect the high-beam headlamps, marker lamps, turn signals, or fog lamps.

General Motors will provide its plan for remedying the defect and its schedule for notifying dealers and owners as soon as they are confirmed.

This is a courtesy notification to dealers. Dealers will be advised when the recall bulletin is scheduled for release.

The Investigate Vehicle History screen in the Global Warranty Management system will be loaded in the near future for this upcoming safety recall. This action has been taken to assist dealers with determining which vehicles are involved so they can properly respond to customer inquiries. Please note the "N/A" under Release Date and the "Incomplete – Remedy Not Yet Available" message under Status. This means release of the recall bulletin is still pending and dealers should not attempt to perform any repairs at this time.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES